

Detroit District Operations Office P.O. Box 1027 Detroit, MI 48231-1027 (313) 226-6797 FAX - (313) 226-3519

Notice to Navigation Interests

Notice No. L07-38 Date: 23 JULY 2007

Waterway: LAKE HURON Location: MICHIGAN

CELRE-OT-T


CONDITION OF FEDERAL NAVIGATION CHANNEL LEXINGTON HARBOR

- 1. Surveys performed during July 2007 indicate shoaling in the Federal navigation channel at Lexington Harbor, Michigan. As shown on reverse. The surveys are available on our web site. Our internet address is: http://www.lre.usace.army.mil/who/operationsofficehomepage/
- 2. Mariners are urged to use extreme caution in the area.
- 3. Questions regarding this notice may be directed to our Operations Office.

WILLIAM J. LEADY Lieutenant Colonel, U.S. Army District Commander

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2007.



LEXINGTON

OLEXING.BMP

THE INFORMATION DEPICTED ON THIS DRAWING REPRESENTS THE RESULTS OF SURVEYS MADE ON THE DATES INDICATED AND CAN ONLY BE CONSIDERED AS INDICATING THE GENERAL CONDITIONS EXISTING AT

ELEVATIONS AND PROJECT DEPTHS ARE REFERRED TO IGLD, 1985 WHEN LAKE HURON IS AT ELEVATION 577.5 FT. ABOVE MEAN WATER LEVEL AT RIMOUSKI, QUEBEC.

SURVEYED: July 2007

LEXINGTON HARBOR, MI

CONDITION OF CHANNEL

ISSUED: 23 July 2007

U.S. Army Engineer District, Detroit